



HEXO Limited
Kemp House
160 City Road
London
EC1V 2NX

Tel: 0207 315 4151
Email: info@hexo-services.co.uk
Web: www.hexo-services.co.uk
Company Reg: 11071511
VAT No: 317397973



QUOTATION

Quote Number	HX-5981
Related EICR	HX-5981
Quote Date	10/11/2020

Client	Jebb Avenue Management Company Limited
Property Address	Jebb Avenue, London SW2 5XL

EICR Items	EICR Code	Description of repair	Cost Exc. VAT
2	C2	Replace damaged metal clad switch Block 52-55. Replace damaged and loose bulkhead light Block 52-55. Blank off switch Block 56-59. Replace bulkhead with missing cover Block 36-47. Replace metal clad switch Block 36-47. Replace metal clad switch Block 64-67. Replace loose bulkhead light Block 94-99.	
3	C2	Install containment around exposed VRI cables in Blocks 52-55, 56-59, 48-51, 36-47.	
4	C2	Install besa box lid Block 52-55, Install missing angle cover Block 56-59, Install missing angle cover Block 36-47. Install metal lid to enclosure x2 Block 60-63 and x1 Block 36-47.	
5	C2	Replace fuse box in Block 94-99 for modern consumer unit. Please note there is suspected asbestos in the fuse carriers of the fusebox.	
6	C2	Switch rooms unlocked with no padlock Block 76-81 and 2x enclosure on stairwell unlocked in Block 35-47. Client to install padlocks. Not included.	£0.00
7	C3	VRI cable to be removed and rewired. Client to arrange contractor as we do not provide a rewiring/installation service. Not included.	£0.00
		Issue satisfactory EICR and associated paperwork.	£0.00
Total Cost Exc VAT			£2,410.00
VAT Amount @ 20%			£482.00
Total Cost Inc VAT			£2,892.00

Quotations are valid for 30 days.

Payment is required in advance and at the booking stage.

If you have any queries with this quotation please contact us and we will be happy to help.

To place your order please contact us and we can arrange a suitable date and then finalise your booking.